

APPENDIX C
PHOTOGRAPHIC DOCUMENTATION



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-Superfund Technical Assessment and Response Team (Mini-START) personnel collecting groundwater sample SB-3-GW with a Geoprobe®.	Photograph Number: 1
Direction: West	Photographer: Jeff Pritchard	Date: 03/08/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Geoprobe® soil sampling at SB-4.	Photograph Number: 2
Direction: South	Photographer: Jeff Pritchard	Date: 03/09/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel packaging soil samples from SB-4.	Photograph Number: 3
Direction: Northwest	Photographer: Jeff Pritchard	Date: 03/09/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of soil core from SB-4.	Photograph Number: 4
Direction: NA	Photographer: Jeff Pritchard	Date: 03/09/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Geoprobe® soil sampling at SB-15.	Photograph Number: 5
Direction: West	Photographer: Jeff Pritchard	Date: 03/10/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel collecting surface soil samples on BNSF property that borders the western edge of the Alter Scrap Yard – North Yard.	Photograph Number: 6
Direction: South	Photographer: Jeff Pritchard	Date: 03/10/2010




Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel collecting groundwater sample SB-17-GW.	Photograph Number: 7
Direction: West	Photographer: Jeff Pritchard	Date: 03/10/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel collecting groundwater sample SB-3-GW.	Photograph Number: 8
Direction: East	Photographer: Jeff Pritchard	Date: 03/08/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel collecting a surface soil sample at SB-15.	Photograph Number: 9
Direction: West	Photographer: Jeff Pritchard	Date: 03/10/2010



Client: Environmental Protection Agency Region 7	Description: Photograph of Mini-START personnel collecting a surface soil sample on BNSF property that borders the western edge of the Alter Scrap Yard – North Yard.	Photograph Number: 10
Direction: East	Photographer: Jeff Pritchard	Date: 03/10/2010