

Salt Creek Water Quality Studies



Photo No.11 Location: SS5/BSS5 below Little Salt Creek looking northwestward and downward from stream bank.
Photo Date: 8/19/98 Approx. Flow: 118 cfs (assume same as USGS at 70th St.)



Photo No.12 Location: SS6 56th St. (Hwy. 77) bridge looking westward (upstream).
Photo Date: 8/19/98 Approx. Flow (USGS): 118 cfs (assume same as USGS at 70th St.)